

## Stainless Steel Works

### Liverpool Street Station



Before



During



After

**W**e were asked to make repairs to a number of walls at Liverpool Street Station that had become scuffed or damaged from luggage and the high volume of commuters that travel through the station each day. We therefore sourced, manufactured and installed a number of stainless steel panels to key areas in the station to help protect the heavily-used areas from further damage in future.



Before



After